

4.0 APPENDIX A - HISTORIC PHOTOS

This appendix contains the historic photographs collected by Mary Jo Morelli applicable to the A.T. Smith House. The photos are presented in chronological order. Captions have been added to help explain the images.



Figure 1. One of the earliest photographs of the A.T. Smith House, most likely taken around 1900. The lack of a south side porch is evident along with a tall chimney flue coming out of the one-story roof near the connection between the living room and kitchen. One 6/6 window is barely visible to the left of the front door.



Figure 2. Mary (Bailey) Clark feeding sheep off of the rear steps around 1900. This is the south entry prior to the porch construction. The lack of windows and shadow cast by the sun verify that it is the south entry. This is the best photo available to help with reconstruction of the entry.



Figure 3. This early photo (early 1900s) shows the southwest corner of the house over the barn. The tall chimney flue from the kitchen area is evident.



Figure 4. The original cabins of A.T. Smith. Photo from early 1900s.



Figure 5. The house taken from the southeast after the open porch has been constructed at the south entry. Taken probably around the 1920s. Note the pile of snow on the front door steps. In Oregon, the "front" door was rarely used and then used only on special occasions. Photo courtesy of WCHS.



Figure 6. The east façade or front of the A.T. Smith House. The photo was made after the open porch was built on the south side but before the replacement of the 6/6 window to the left of the front door. Taken probably around the 1920s. The tall chimney flue is barely evident. Note the horizontal rail fence. Photo courtesy of WCHS.



Figure 7. This one of two 1934 Historic American Building Survey (HABS) photos taken of the house. An open south porch has been constructed to shelter the entry. This is the best photo of the tall chimney flue serving the kitchen (and possibly the living room) and of the southeast 6/6 windows before removal.



Figure 8. This is the second of two 1934 HABS photos taken of the A.T. Smith House. This shows the rear of the house along with the exterior chimney that replaced the original interior chimney and was installed to vent the basement furnace in the late 1920s. Also visible is a collapsing gabled structure used to shelter the basement entrance.



Figure 9. This is the front of the house in 1971. The kitchen/living room chimney flue has been removed and the window to the left of the front door substituted for a larger 16-pane fixed window.



Figure 10. This is the rear of the house in 1971. The gable structure used to protect the basement stairs has been removed, along with its stairs and opening, but its shadow remains. Both the west and north exterior doors are completely overgrown.